


Class 6 Self-Adhesive Indicators

STOP!

be sure...be ParaSure

Self Adhesive
CLASS 6



Unprocessed
indicator
Ready for use


Self Adhesive
CLASS 6



PASS

Items in tray/pack
can be safely used

Self Adhesive
CLASS 6



PASS

Items in tray/pack
can be safely used

Successfully processed indicators
Colour has changed to teal or darker


Self Adhesive
CLASS 6



FAIL

Do NOT use items
in tray/pack

Self Adhesive
CLASS 6



FAIL

Do NOT use items
in tray/pack

Self Adhesive
CLASS 6



FAIL

Do NOT use items
in tray/pack

Unsuccessfully processed indicators
Evidence of original purple colour

PS1210 3.5 minutes at 134°C
PS1220 4.0 minutes at 134°C

PS1230 5.3 minutes at 134°C
PS1240 7.0 minutes at 134°C